

TOP SECRET

FROM: Mission Coordinator

28 JULY 1967

SUBJECT: Mission Alert Notification

TO: (See Below)

Request your attendance at the Commander's Briefing to be held in the Operations Briefing Room on 28 JULY 1967 at

1145 L. The briefing concerns the following:

1. Mission Code Name and Number: BX 6711
2. Date/Time of Launch (H-Hour): 29 10215Z 1115 L.
3. Ground Spare (H+1:00): 29 10315Z 1215 L.

23X1/Bases: Takeoff KADENA Staging — , Landing KADENA.

6. Ground Spare Requirements: SAME AS PRIMARY
EXCEPT SIP INSTEAD OF SYSTEM VI

7. Special Instructions/Comments: MODIFIED BLACK-SHIELD GANNED MSN # 14

FOR THE COMMANDER

Mission Coordinator

Office	Time(L)	Recipient	Office	Time(L)	Recipient
CMDR			DCOL		
DCO			DCOC/MC		
DCM			DCOMI		
DCS			DCOW		
SECUR			COMMO		
FLT SURG			AFCS		(Notify Only)
DCOM			TTFC(SAC)		(Notify Only)

TOP SECRET

14 COPIES

Current as of 14 July 1967

29 July 67 6711
Approved For Release 2001/03/02 : CIA-RDP69B00041R002200100003-1

1115 L T.O.
1815 L INITIAL
0745 L FINAL

	<u>P.P.</u>	<u>AK</u>	<u>HANGER</u>
1.	MV-	131	1
2.	DS-	129	3

25X1A

Approved For Release 2001/03/02 : CIA-RDP69B00041R002200100003-1

Approved For Release 2001/03/02 : CIA-RDP69B00041R002200100003-1

JAC

FULL PRESSURE SUIT TEST LOG

Secondary

SUBJECT # 1054FLIGHT DATE 29 July 67SUIT # - 3DON OUTER GARMENT W/FLOAT GEAR - 3DOFF HELMET # - 4TIME IN SUIT

25X1A

GLOVES # - 6TECHNICIAN BOOTS 2PRESS-TO-TESTPRE-FLIGHTSUBJECT TESTPOSTFLIGHTSYSTEM #1

Max Pressure

110110110

Differential

1.21.41.2

Leak Rate

1100300500SYSTEM #2

Max Pressure

120120120

Differential

1.41.41.2

Leak Rate

700200550

Unpress Leak Rate

4500600450

Face Heat

18

Comm and Cord

ok

Pencils

✓

Knife

✓

Controller Number

✓

Packet

✓

Grease Zippers

✓Check Location of CO₂✓

Pressure Tap Screws

✓

PRESSURE SUIT HOOK-UP AND CHECKLIST

- ✓ 1. Packet in pocket.
- ✓ 2. Stirrups secured.
- ✓ 3. Communication secured and functioning.
- ✓ 4. Face heat on (medium).
- ✓ 5. Oxygen hoses secured in QD.
- ✓ 6. Three harness snaps secured - harness adjusted and surplus stowed.
- ✓ 7. Kit adjusted and surplus stowed.
- ✓ 8. Two (2) bailout hoses secured.
- ✓ 9. Lap belt, shoulder harness, key secured and adjusted.
- ✓ 10. Oxygen hoses under right leg strap, chest strap under helmet-hold-down.
- ✓ 11. Emergency oxygen lanyard secured and pin removed.
- ✓ 12. Green apple secured.
- ✓ 13. Red knob secured.
- ✓ 14. Manual over ride handle secured.
- ✓ 15. Two (2) rocket jet releases secured.
- ✓ 16. Check face heat.
- ✓ 17. Press-to-test both oxygen systems.
- 18. LOW oxygen pressure - #1 system 70/80 #2 system 75/80.
- 19. HIGH oxygen pressure departing #1 system 9.5 #2 system 9.5.
Readjust lap belt
- 20. Foot rest guards over seat foot rests. 11202
- 21. *Hook Raft Lanyard*
- SUBJECT 1054 AIRCRAFT NUMBER 129.
- TECHNICI [REDACTED] DATE OF FLIGHT 29 JULY 67.
- HIGH oxygen pressure returning #1 system _____ #2 system _____.

25X1A

Grd Spare

EQUIPMENT PREFLIGHT FOR HIGH FLIGHT

PARACHUTE

- ✓ 1. Ripcord pins seated (main and first stage).
- ✓ 2. Check power cable linkage.
- ✓ 3. Pack opening elastics secured.
- ✓ 4. First stage jettison arched and pins secured.
- ✓ 5. Two (2) rocket jet units secured.
- ✓ 6. Manual over ride handle secured.
- ✓ 7. Green apple secured.
- ✓ 8. Red knob secured.
- ✓ 9. Bailout hoses adjusted for pressure suit.
- ✓ 10. Bailout hose connectors operating.
- ✓ 11. Harness adjusted for HIGH flight.
- ✓ 12. Automatic opener - triggered and reset.
- ✓ 13. Aneroids 1400' to 7400'.
- ✓ 14. Bailout cylinder pins secured.
- ✓ 15. Bailout cylinder pressure #1 1860 #2 1860
- ✓ 16. Communication cord secured to chute.
- ✓ 17. Visual inspection completed.

SURVIVAL KIT

- ✓ 1. Yellow handle secured.
- ✓ 2. Trigger clearance.
- ✓ 3. Kit disconnects secured.
- ✓ 4. Lid secured.
- ✓ 5. Visual condition.

INSTALLATION

- ✓ 1. Vent secured at disconnect.
- ✓ 2. Kit secured to chute - loose.
- ✓ 3. Emergency oxygen lanyard secured to chute and pin installed.
- ✓ 4. Communication cord secured at disconnect.
- ✓ 5. Vent hose secured to chute.
- ✓ 6. Pin secured in QD and safetied.
- ✓ 7. Oxygen system low pressure #1 70/75 #2 70/75
- ✓ 8. Flip pin in "D" ring.
- ✓ 9. Stirrup cables extended and operating freely.
- ✓ 10. Foot rest guards over seat foot rest.

25X1A

SUBJECT 1054 129
 TECHNICAL [REDACTED] 29 56467
 SEAT KIT NUMBER 54 103
 TYPE CUSHION HP5B 71

25X1A

Approved For Release 2001/03/02 : CIA-RDP69B00041R002200100003-1

Approved For Release 2001/03/02 : CIA-RDP69B00041R002200100003-1

DATE 29 July 67 ACFT 131 PILOT [REDACTED]
TIME IN FLIGHT 1+15 TIME IN SUIT 2+45 PREBREATHING TIME 1+00

SATISFACTORY

UNSATISFACTORY

1. PHYSICAL CONDITION (PILOT)

2. SURVIVAL KIT AND CUSHION #51 HPSB3. PARACHUTE SIN4. HELMET P. II 266

A. REFLECTIONS

B. FACE HEAT

C. COMMUNICATIONS

5. SUIT PROPER - 3A. CABIN DECOMPRESSION: YES NO6. OUTER GARMENT - 37. BOOTS AND SPURS, Q.D. type8. GLOVES - 2

9. OXYGEN SYSTEM

DEPART		RETURN	
TIME	AMT	TIME	AMT

#1 1030 9. 1230 8.75#2 1030 9. 1230 9.

10. MISCELLANEOUS

11. EVALUATION ITEMS

A.

B.

C.

D.

E.

12. REMARKS: (EXPLAIN UNSATISFACTORY REPORT)

SUBJECT # 1051 FLIGHT DATE 29 July 67
 SUIT # 3 DON _____
 OUTER GARMENT W/FLOAT GEAR 3 DOFF _____
 HELMET # 266 TIME IN SUIT _____
 GLOVES # 2 TECHNICIAN _____
 BOOTS 1 _____

PRESS-TO-TEST

PRE-FLIGHT

SUBJECT TEST

POST-FLIGHT

SYSTEM #1

Max Pressure 106 104 106
 Differential 1.2 1.2 1.2
 Leak Rate 800 600 200

SYSTEM #2

Max Pressure 110 120 110
 Differential 1.2 1.2 1.2
 Leak Rate 1300 600 1200
 Unpress Leak Rate 300 500 200

Face Heat 180 _____
 Commo and Cord OK _____
 Pencils ✓ _____
 Knife ✓ _____
 Controller Number ✓ _____
 Packet ✓ _____
 Grease Zippers ✓ _____
 Check Location of CO₂ ✓ _____
 Pressure Tap Screws ✓ _____

PRESSURE SUIT HOOK-UP AND CHECKLIST

- ✓ 1. Packet in pocket.
- ✓ 2. Stirrups secured.
- ✓ 3. Communication secured and functioning.
- ✓ 4. Face heat on (medium).
- ✓ 5. Oxygen hoses secured in QD.
- ✓ 6. Three harness snaps secured - harness adjusted and surplus stowed.
- ✓ 7. Kit adjusted and surplus stowed.
- ✓ 8. Two (2) bailout hoses secured.
- ✓ 9. Lap belt, shoulder harness, key secured and adjusted.
- ✓ 10. Oxygen hoses under right leg strap, chest strap under helmet-hold-down.
- ✓ 11. Emergency oxygen lanyard secured and pin removed.
- ✓ 12. Green apple secured.
- ✓ 13. Red knob secured.
- ✓ 14. Manual over ride handle secured.
- ✓ 15. Two (2) rocket jet releases secured.
- ✓ 16. Check face heat.
- ✓ 17. Press-to-test both oxygen systems.
- ✓ 18. LOW oxygen pressure - #1 system 80/85 #2 system 85/90.
- ✓ 19. HIGH oxygen pressure departing #1 system 9 #2 system 9.
- ✓ - *Readjust lap belt*
- ✓ 20. Foot rest guards over seat foot rests. 1030
- ✓ 21. *Hook Red Lanyard*
- SUBJECT 1051 AIRCRAFT NUMBER 131
- TECHNICIAN [REDACTED] DATE OF FLIGHT 29 July 67
- HIGH oxygen pressure returning #1 system 8.75 #2 system 9.

1230

EQUIPMENT PREFLIGHT FOR HIGH FLIGHT


PARACHUTE

- ✓ 1. Ripcord pins seated (main and first stage).
- ✓ 2. Check power cable linkage.
- ✓ 3. Pack opening elastics secured.
- ✓ 4. First stage jettison mated and pins secured.
- ✓ 5. Two (2) rocket jet units secured.
- ✓ 6. Manual over ride handle secured.
- ✓ 7. Green apple secured.
- ✓ 8. Red knob secured.
- ✓ 9. Bailout hoses adjusted for pressure suit.
- ✓ 10. Bailout hose connections operating.
- ✓ 11. Harness adjusted for HIGH flight.
- ✓ 12. Automatic openers triggered and reset.
- ✓ 13. Aneroids 1400' to 7500', *See bench*
- ✓ 14. Bailout cylinder pins secured.
- ✓ 15. Bailout cylinder pressure #1 1800 1800
- ✓ 16. Communication cord secured to chute.
- ✓ 17. Visual inspection completed.


L/P #1
SURVIVAL KIT

- ✓ 1. Yellow handle secured.
- ✓ 2. Trigger clearance.
- ✓ 3. Kit disconnects secured.
- ✓ 4. Lid secured.
- ✓ 5. Visual condition.

INSTALLATION

- ✓ 1. Vent secured at disconnect.
- ✓ 2. Kit secured to chute - loose.
- ✓ 3. Emergency oxygen lanyard secured to chute and pin installed.
- ✓ 4. Communication cord secured at disconnect.
- ✓ 5. Vent hose secured to chute.
- ✓ 6. Pin secured in QD and safetied.
- ✓ 7. Oxygen system low pressure #1 75/80 75/80
- ✓ 8. Pip pin in "D" ring.
- ✓ 9. Stirrup cables extended and operating freely.
- ✓ 10.  Cool rest

25X1A

SUBJECT 1051 AIRCRAFT NUMBER 131
 TECHNICIAN  DATE OF CHECK 29 JULY 67
 SEAT KIT NUMBER 51 PARACHUTE NUMBER 106
 TYPE CUSHION HP5B 76

25X1A

*** TOP SECRET ***

DCOL CHECK LIST

* DENOTES MANDATORY CALL TO COMMAND POST UPON COMPLETION

H-24:00 TO H-23:30: SECURE SUITS, CHUTES, KITS AND VENT UNITS:

DESIGNATE LIFE SUPPORT TECHNICIANS

M.V. 171131

D.S. 171131

H-23:30: ATTEND COMMANDERS BRIEFING:.....

SUBMIT HANGAR ACCESS ROSTER, 5 CYS 1-MC 3-SECURITY 1-DCOL.....

SUBMIT RECOVERY ROSTER, 3 CYS 1-MC 1-ADMIN 1-DCOL.....

H-22:00 TO H-21:30: COORDINATE WITH INTELLIGENCE AND SURVIVAL PERSONNEL ON

SURVIVAL AND E&E ITEMS:.....

H-22:00 TO H-17:00: PREFLIGHT:

BOTH SUITS (EA PILOT).....

PARACHUTE AND EMERGENCY O2 SYSTEMS.....

SEAT KIT COMPONENTS.....

SUIT ROOM VENT.....

LOX VENT UNIT.....

OXYGEN CYLINDERS.....

TEST EQUIPMENT.....

TRANSPORT VANS.....

H-20:00: NOTIFY SECURITY, SEAT KIT AVAILABLE FOR PACKING:.....

H-3:00 TO H-1:40: PREPARE PREBREATHING ROOM FOR RECEIPT OF PILOT:.....

H-2:00 PERSONALLY CHECK WITH MISSION COORDINATOR AT C.P. TO VERIFY NAMES OF

PRIMARY AND SPARE PILOTS AND AIRCRAFT:

P.....

S.....

INSTALL SEAT KIT AND PARACHUTE:.....

H-2:00: RECEIVE PACKET FROM INTELLIGENCE.....

H-1:45 TO H-1:30: SECURITY INSPECTS SUITS:.....

H-1:40 TO H-1:25: FLIGHT SURGEONS MEDICAL IN DCOL:.....

H-1:20 TO H-1:10: DRESS PILOT, PRESSURE CHECK EQUIPMENT:.....

H-1:10 TO H-1:05: PREPARE FOR PILOT TRANSPORT:.....

*H-1:05 TO H-1:00: TRANSPORT TO AIRCRAFT:.....

*H-1:00 TO H-0:45: PILOT HOOKUP AND SUIT A/C CHECK.....

H-0:45 TO TAKEOFF: STANDBY IN DCOL AND PACK LOW RECOVERY EQUIPMENT:.....

LANDING: REMOVE PILOT, TRANSPORT PILOT BACK TO DCOL, DESUIT PILOT:.....

DEBRIEF PILOT, EVALUATE AND CHECK RELIABILITY OF EQUIPMENT:.....

POST-FLIGHT EQUIPMENT:.....

*** TOP SECRET ***

Local Time

1115-1145

1145

1315-1345

1315-1345

1515

0815-0735

0915-

0915

0915

0930-0945

0935-0950

0955-1005

1005-1010

1010-1015

1015-1030

1115

M.C.
AK!

25X1A

D.S.

1055-1105

1105-1110

1110-1115

1115-1130

1215